

THOMPSON AIRCRAFT



Management and Pilot Services

1982 MITSUBISHI DIAMOND 1A



**A022SA
N400UF**

**TOTAL TIME:
5412 Hours**

**LANDINGS:
5072**

**ENGINES:
Since New
5307/5578**

**Cycles Since New
4894/5140**

**SMOH
2280/2183**

**Since HOTS
504/459**

**CALL FOR PRICING
512-864-4292**

AVIONICS

Garmin GNS 400 GPS
RVSM Certified
GMX 200 Multi Function Display
w/vertical profile Radar and XM Weather
Dual Collins VIR 30A Navs
Traffic Awareness System(TAS)
B&D Cockpit Voice Recorder
Dual Collins VHF 20A Comms
Collins DME-40
Collins ALT 55 Radio Altimeter
Dual Collins TDR 90 Transponders
Honeywell TAWS
Dual Collins ADF 60
Moving Map w/DVD
XM Audio

ADDITIONAL FEATURES

Branson Fuselage Fill System
Branson Tailcone Baggage Compartment
Logo Lights
Freon Air Conditioning STC#SA5933SW
Concorde Lead Acid Battery Upgrade Branson
Landing Weight Increase
Rosemont Model 0872CTL Ice Detector System

INTERIOR

Seven passenger Condor Gray leather interior with aft baggage.
New July 2003.

EXTERIOR

Overall Matterhorn White with Ocean Blue, Wine and Silver striping.
New July 2003.

*Note: Aircraft overran runway in 1990.
Call for details.

*SPECIFICATIONS AND TIMES SUBJECT TO
VERIFICATION UPON INSPECTION.*

04/12/12 MAT

www.thompsonaircraft.com

A022SA
N400UF

THOMPSON
AIRCRAFT 
Management and Pilot Services

1982 MITSUBISHI DIAMOND 1A



INTERIOR
COCKPIT



www.thompsonaircraft.com